

CNC Cable

AdvanceCut 45



XXXXXXXXXXXXXXXXXXXX

XXXXXXXXXXXXXXXXXXXX

**** Important –**

Ensure any remaining non connected spade terminals of the cable are individually insulated with heat shrink or electrical tape.